

DECATHLON recall EDR CF ULTRA 105 DI2

EDR CF ULTRA 105 DI2

Model codes concerned : Light Blue 8902428 & Green 8817920

Item codes : 5306671 / 5306672 / 5306673 / 5306674 / 5306675 / 5306676

4928585 / 4928586 / 4928587 / 4928588 / 4928589 / 4928590

Sales period concerned : du 01/07/2025 au 18/03/2026



Why is the product dangerous ?

One too many spacers have been assembled, which can lead to a risk of stem pivoting, and which could, in the long term, cause deterioration of the fork steerer tube

What should I do ?

Please stop using the bike and take it to a Decathlon workshop to have it repaired.

Recourse available to consumers

The EDR CF ULTRA 105 DI2 will be taken care of and repaired free of charge under warranty (removal of the excess spacer and compression of the headset)

Contact

Our customer relations centre is available to answer all your questions on: 032 756 70 70, Monday to Friday: 9 am to 6 pm, Saturday: 9 am to 12:30 pm and 1:30 pm to 5 pm.

Thank you for your understanding and we apologise for any inconvenience caused.